



ENVIRAL® Oberflächenveredelung GmbH · Altdorfer Weg 6 · D-14823 Niemegek



Oberflächenveredelung GmbH

Wir danken für Ihr Vertrauen!

Altdorfer Weg 6 | info@enviral.de
D-14823 Niemegek | www.enviral.de

Telefon +49 (0) 33843 642-04
Telefax +49 (0) 33843 642-24

kostenlose Servicenummer
0-800/ENVIRAL 0-800/368 47 25

All technical recommendations for application we give to our clients to the best of our knowledge and according to the state of the art are not binding. According to our General Terms and Conditions of Business they do not establish any contractual legal relationship and no ancillary obligations resulting from the purchase contract. This does not release the client from his/her own responsibility to check our services, products and recommendations with regard to their suitability for the intended use. Our General Terms and Conditions of Business apply, which you can view at any time at www.enviral.eu.

DATA SHEET ENV 802 – Repairs

Instructions for repairing powder-coated surfaces with liquid paint systems

For various reasons, overcoating or painting of powder-coated surfaces may become necessary. Preferably, this should be done in the same powder coating quality, if the parts can be removed and cured again. Permanently installed parts, on the other hand, are not suitable for powder coating. In this case, liquid paint systems are used, which must be applied on site.

Repair coating with liquid paint systems:

For damages which do not reach the substrate and recoating of intact powder coatings:

1. Always sand parts wet with 320 grit sandpaper (blind); the substrate is not to be damaged in the process.
2. Remove sanding dust with clear water (without additives).
3. After proper drying, wipe with dust-binding cloth.
4. Overcoating by spraying or rolling with 2-component PUR lacquer paint. For metallics, spray painting is preferable.
The repair coating must be applied over the entire visible surface, as this is the only way to achieve a decoratively uniform color appearance.
5. The coating can only be applied in dry weather (temperatures not below 15°C) and on an absolutely clean and dry substrate.

For damage that extends to the substrate:

1. Sand surfaces wet with 320 grit sandpaper (blind). All loose particles of paint must be completely removed and the substrate under the damaged areas must be sanded to a bright metallic finish.
2. Wash off with isopropyl alcohol or white spirit. After proper drying, wipe off with a dust-binding cloth.
3. Coating with 2-component epoxy primer by spraying or rolling. After drying (above 15°C), the 2C PUR lacquer paint can be applied by spraying or rolling. For metallic systems, the spray process is to be preferred. The repair coating must be applied over the entire visible surface, as this is the only way to achieve a decoratively uniform color appearance.

Observe the processing instructions of the respective liquid coating system.
There is no warranty on repair work.

Sealant adhesion: According to sealant adhesion on powder-coated surfaces of facades, as of 01 / 2021 (compare data sheet ENV 803)